

Known technical solution for a motorized zoom (e.g., operation microscope)

A schematic diagram of a vertical mechanical assembly. A central vertical shaft has several components. At the top, a horizontal bar is labeled F1 and F2. Below it, a horizontal bar is labeled L3. Further down, a horizontal bar is labeled AS2/MN. Below that, a horizontal bar is labeled L2. Further down, a horizontal bar is labeled AS1/MN. At the bottom, a horizontal bar is labeled L1. On the left side, a curved line is labeled LA2 and LA1. A box labeled AE is connected to the bottom of the assembly by a curved line. Arrows indicate movement: horizontal arrows between the top bars and vertical arrows between the middle bars.

Fig. 5




Fig. 3




Fig. 4

